

# 一胜百模具技术（上海）有限公司

2023-07-20

一胜百模具技术（上海）有限公司

职业病危害因素检测报告信息公开表

单位名称	一胜百模具技术（上海）有限公司	
检测类型	<input type="checkbox"/> 评价 <input type="checkbox"/> R 定期 <input type="checkbox"/> 监督 <input type="checkbox"/> 事故	
地址	上海市闵行区申富路18号	
建设项目存在的 职业病危害因素	存在的主要职业病危害因素	噪声、氢氧化钾、高温、过氧化氢、其他粉尘、游离二氧化硅、镍及其无机化合物（按Ni计）、铬及其无机化合物（按Cr计）、钼及其化合物（按Mo计）、锰及其无机化合物（按MnO2计）、激光辐射、砂轮磨尘、工频电场
	检测结果	化学因素 19 个，物理因素 40 个，生物因素 0 个，合格的检测点位 59 个，不合格的检测点位 0 个。  合格的职业病危害因素为 59，不合格的职业病危害因素为 0。
	技术服务项目组人员	刘山山
	现场调查、采样、检测的专业技术人员	现场调查：刘山山、薛轶  采样：高一鸣、曾秋霞  检测：史志倩、沈嵩峰
	建设单位联系人、陪同人员	联系人：乔佳  陪同人员：乔佳
	现场调查、采样、检测的时间	现场调查时间：2023.6.27  采样时间：2023.6.27  检测时间：2023.6.27-2023.7.7

注：涉及国家秘密、商业秘密、技术秘密及个人隐私的信息和法律、法规规定可不予公开的除外。

现场影像资料








**ASSAB**

### 进入工作现场须知

#### NOTICE OF ENTERING WORK SITE

外来人员未经许可，不得进入工作现场！ UNAUTHORIZED PERSONNEL SHALL NOT ENTER THE WORK SITE.	
遵从接待人员的引领！ PLEASE FOLLOW VISITOR GUIDE'S INSTRUCTIONS.	
衣冠不整者，不得进入工作现场。 IMPROPERLY DRESSED PERSONNEL SHALL NOT ENTER THE WORK SITE.	
穿戴好安全防护用品！ PLEASE WEAR YOUR SAFETY PROTECTIONS.	
按路标指示行走安全通道。 PLEASE WALK ON THE SAFE WALKWAYS ACCORDING TO THE SIGNS.	
注意避让行车、叉车等移动特种设备！ PLEASE PAY ATTENTION TO THE SPECIAL MOBILE EQUIPMENTS SUCH AS CRANES, FORKLIFTS, ETC.	
着高跟鞋、拖鞋不能进入场地。 WEARING HIGH-HEELS AND SLIPPERS SHALL NOT ENTER THE WORK SITE.	
不可触摸各类开关、设备、工装及料件！ DO NOT TOUCH THE SWITCHES, EQUIPMENTS, FROCKS AND MATERIALS.	
未经许可，不许拍照！ DO NOT TAKE PHOTOS WITHOUT PERMISSIONS.	

**请遵守各工作现场的特殊规定**  
PLEASE FOLLOW THE SPECIAL REGULATIONS IN EACH